

KB-0118-Entering BIOS on HP units

GENERAL

Distribution	OEM/Partner/Distributor	Installer	Customer
	YES	YES	YES
Last Update	25-03-2010		
Product	WebCCTV - HP Unit		
Version	any		

DESCRIPTION

Sometimes it is not possible to enter the BIOS of the HP Unit. The reason of the problem is PS2 keyboard.

SOLUTION

To fix the problem, please connect USB keyboard to the computer and you will be able to enter BIOS.